

4100-12R

Sharp Tip Sternal Ring Rake



Caution:

Always stabilize the single rake by hand to elevate and expose operative site. Failure to do so may result in rake slipping.

Rultract Inc. 5663 Brecksville Rd. Cleveland, Ohio 44131 U.S.A.
Website: www.rultract.net Email: rultract@aol.com
Phone: 888-550-5695 / 440-376-2077 / 330-856-9808

